

Quality & Compliance in a Fabric First Approach: Internal Wall Insulation

Presented by **Dean Owen**, Head of Business Development & Technical Specification

TIMELINE

Community
Energy Saving
Programme
(CESP)

1 October 2009 to 31 December 2012

January 2013

ECO 1

April 2015

ECO 2

October 2018

ECO 3

April 2022

ECO 4

2020/2022


RIRI / UFI => 25-year warranties

SYSTEM DESIGNER INSULATION SOLUTIONS











QUALITY & COMPLIANCE









SWIP APPROVED CONTRACTOR SCHEME

Sc

Social Housing/Local Authorities

Retrofit Assessors/ Coordinators

Principal Contractors

(6)


Installers



DIY market

SWIP APPROVED CONTRACTOR SCHEME





TECHNICAL SUPPORT SERVICE



SWIP WARRANTY


24/48h

6

Timeframe for application processing

Team members managing quality and compliance

- Online application
- Portfolio of installation photographs reviewed and scrutinised
- Material sales vs warranty application review
- No SWIP Warranty = No Guarantee!




GUARANTEE PROVIDERS









100% technical monitoring




4 Internal Technical Monitoring managers – desktop video call assessments / reports



4 External Regional Technical
Managers – North / Scotland &
Midlands/ Southeast & Southwest



Warranties & Inspections logged / recorded against each installer and company



GOVERNMENT ACTION – INDUSTRY RESPONSE



Industry-led – IAA, TrustMark, Cert Bodies, System Designers



Retrospective inspections on all ECO 4 SWIP work carried out



SWIP inspection only where SWIP Warranties issued



Remedial action (if required) SWIP support / Guidance

ofgem



1728_1086232001_06016_1030





The Office of Gas and Electricity Markets 10 South Colonnade Canary Wharf London, E14 4PU www.ofgem.gov.uk

5 February 2025

Important notice of home check

Please keep this letter.

Unique Measure Reference number: P216151KJHM

Dear resident,

We are writing to inform you that your home may be selected for a check of its wall insulation.

Reason for letter

Your home had internal and/or external wall insulation installed after 1 April 2022 under one of the government's current Energy Company Obligation (ECO) schemes, ECO4 or the Great British Insulation Scheme (GBIS).

Problems have been identified with the quality of these types of insulation in some homes. In response, the government has announced checks of homes which might be affected. You can read the full guidance here: www.gov.uk/insulation-check. As Ofgem is the administrator of the schemes we are contacting you about the next steps.

If you're a tenant, please let your landlord know about this letter. You may need to allow access for any further works in line with your tenancy agreement.

CAUTIOUS INDUSTRY APPROACH

RC, C2, on-site presence & C3 inspections

Know the systems you are funding!

Remedial action (if required) SWIP support / Guidance

Managing risk, legacy

U-value & condensation risk request via cert bodies and guarantee providers

SWIP inspections only where SWIP Warranties issued

Protect the industry long-term









Thank you!

Communicate, Collaborate, Standards, Protection, Legacy





